DAILY WORK ORDER	
Work Site: Bossert Manufacturing	Work Feriod: 8/04/87
	OSC: Jack D. Harmon
WORK PLANNED/AUTHORIZED: 1.)Continue to clean out sumps (Sumps #35 and #33B) 2.)Begin to laser second floor of areas #10 & #11 3.)Check-out and clean tank of skid unit in level B. 4.)Sample area #13 - first and second floors and areas #14 & #15 pending the dampness of the surfaces. 5.)Decon the manlift and wipe sample. Demobe pending results of analysis 6.)Draw sludge from the clarifier of water treatment system.	Yes No Continues 1.) () () (x) 2.) (x) () () 3.) (x) () () 4.) (x) () () COMMENTS:
A PARTY TO THE PAR	EQUIPMENT USED FROM PREVIOUS DAY: All Authorized COMMENTS:
(1) Response Manager (2) Laborer (1) Lab Technician (2)	(1) Foreman (3) (2) Foreman (2) (1) Field Clerk (4) Clean-up Technician (2) (1) Operator (2)
Contractor Signature:	OSC Signature:
Date: 8/4/87	Date: 8/4/87